RECEIVE BPPI I O YAM



RCHITECTURAL SECTIONNational Fire Protection Association

1 Batterymarch Park, Quincy, Massachusens 02269-9101 USA Telephone (617) 770-3000 Fax (617) 984-7056

SOUTHEAST REGIONAL FIRE CODE DEVELOPMENT COMMITTEE

April 28, 1998

Ms. Geraldine Burdeshaw Secretary, ANSI A 17 Committee ASME International 345 East 47th Street New York, NY 10017-2392

Dear Ms. Burdeshaw:

At its March meeting the Southeast Regional Fire Code Development Committee voted to support the following proposed change to A17.1 Rule 102.2(c)(3).

102.2(c)(3). Means shall be provided to automatically disconnect the main line power supply to the affected elevator upon or prior to the application of water from sprinklers located in the machine room or in the top of the hoistway. This means shall not be self-resetting. The activation of sprinklers outside the hoistway or machine room shall not disconnect the main line power supply.

The committees concern is the shutdown of the elevator while in Phase II Fire fighter service. The loss of power to an elevator during fire fighter use, with no warning or time permitted to take appropriate action, places these fire fighters in danger. The concerns raised by the A17 Committee for requiring this shutdown where sprinklers are installed in shafts is appropriate when the sprinkler is located at the top of the shaft. A sprinkler in the shaft pit does not pose the same hazard and will not adversely affect the operation of the elevator. Fire fighters have for years relied on elevators for fire fighting and rescue operations. If power is lost to elevators and fire fighters become trapped, they may be reluctant to use elevators in the future increasing the potential of injuries, death and dollar loss from the delay in fire fighting activities. We hope you consider this proposal and if you have any questions please feel free to contact me. Thank you for your cooperation in this matter.

Steven F. Sawyer,

Staff Liaison/Senior Fire Service Specialist

u	66~
И	

LA. S.F.M. PLAN KENTEW	e.u.ca
LA. S.P.NI. I	SEVIEWER
=0#	
181G TO	UWNER
SENDER	
COPY WHAT HGS	
34 = 1 = 1 = 1 = 1 = 1 = 1 = 1 = 1 = 1 =	Fire SYSF
3	